

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**



1/16




FIG. 1A




FIG. 1B





FIG. 1C



2/16




FIG. 1D





FIG. 1E



3/16




FIG. 2A




FIG. 2B





FIG. 3A




FIG. 3B



5/16





FIG.3C



6/16




FIG. 3D



7/16




FIG.3E





Serial No.: 10/099,724  
Title: "SHIELDED MULTI-CONDUCTOR INTERCONNECT..."  
Applicant: Murray S. Rodgers, et al.  
Docket No.: 50060-00051  
Attorney: Robert B. Berube,  
Telephone: (303) 338-0997

**8/16**




FIG.4A

**9/16**




FIG.4B



10/16




FIG.4C



11/16




FIG.4D



12/16




FIG.5A



13/16




FIG. 5B



14/16





FIG. 5C



15/16




FIG.6.





16/16




FIG.7